

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of:

Rainer Schneider

Patent No. 7,534,104**Issued:** May 19, 2009**Application No.** 10/781,030**Filed:** February 17, 2004**Confirmation No.** 2830**FILED VIA EFS**ON FEBRUARY 2, 2010**For:** ADAPTER FOR LIGHT EMITTING
APPARATUS USED IN MEDICAL FIELD**Examiner:** Ralph A. Lewis**Art Unit:** 3732**Attorney Reference No.** 5497-67414-01FILED VIA ELECTRONIC FILING SYSTEM
COMMISSIONER FOR PATENTS

REQUEST FOR CERTIFICATE OF CORRECTION

The following printing errors were noted in comparing the printed patent with the papers in the attorneys' files:

In the Specification:

Column 3, line 31, "handpiece system I" should read --handpiece system 1--.

In the Claims:

Column 9, line 57, "offset along a the" should read --offset along the--.


All of the above errors are attributable to the Patent Office, and a proposed Certificate of Correction is enclosed to make formal notice of the errors in the referenced patent. Applicants request that the Patent Office provide a formal Certificate of Correction to correct the errors noted herein.

Respectfully submitted,

KLARQUIST SPARKMAN, LLP

One World Trade Center, Suite 1600
121 S.W. Salmon Street
Portland, Oregon 97204
Telephone: (503) 595-5300
Facsimile: (503) 595-5301

By



Michael P. Girard
Registration No. 38,467

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,534,104
APPLICATION NO. : 10/781,030
ISSUE DATE : May 19, 2009
INVENTOR(S) : Rainer Schneider

Page 1 of 1

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

Column 3, line 31, "handpiece system I" should read --handpiece system 1--.

In the Claims:

Column 9, line 57, "offset along a the" should read --offset along the--.

MAILING ADDRESS OF SENDER:

Klarquist Sparkman, LLP
One World Trade Center, Suite 1600
121 SW Salmon Street
Portland Oregon, 97204